

THOMAS MONTGOMERY BARN AND HOUSE WHITE CLAY CREEK HUNDRED NEW CASTLE COUNTY, DELAWARE

Prepared by

Bernard L. Herman David L. Ames Gabrielle M. Lanier Nancy Van Dolsen

Center for Historic Architecture and Engineering College of Urban Affairs and Public Policy University of Delaware Newark, Delaware






THINK LINE

HISTORIC AMERICAN BUILDINGS SURVEY


INDEX TO PHOTOGRAPHS


Thomas Montgomery Barn White Clay Creek Hundred New Castle County Delaware

David	l L. Am	es, Photographer Fall 1990
DE-	-1	PERSPECTIVE OF NORTHWEST AND SOUTHEAST SIDES, LOOKING EAST
DE-	- 2	NORTHWEST ELEVATION, LOOKING SOUTHEAST
DE-	- 3	PERSPECTIVE OF NORTHEAST AND SOUTHEAST SIDES, LOOKING WEST
DE-	-4	PERSPECTIVE OF SOUTHEAST SIDE, LOOKING NORTHEAST
DE-	-5.	DETAIL OF NORTHWEST ELEVATION





HABS No. (₹) - 2





HABS No.







Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VIC:	VITY					
Delaware			Newark Vicinity					
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Montogomery, Thomas Barn White Clay Creek Hundred HABS NO.								
SECONDARY OR COMMON NAMES OF S'N/A	TRUCTURE	· · · · · · · · · · · · · · · · · · ·						
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)								
Southeast corner, Rte 273 and Eagle Run Road, Newark, Delaware 19711								
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)								
early-to-mid- nineteenth century N/A SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)								
One of the few stone bank barns in New Castle County, Delaware.								
STYLE (<i>IF APPROPRIATE</i>) Bank Barn								
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Rubble stone on all elevations.								
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)								
27'0" by 42'1"								
EXTERIOR FEATURES OF NOTE Feneatration is intact on facade; barn retains its cupola.								
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)								
Lower level retains evidence of early twentieth-century concrete troughs and stalls.								
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Bridge to upper level has been removed; original lower level partitioning was removed; interior framing was replaced during the twentieth century.								
PRESENT CONDITION AND USE		ndelik (dalah dalah gereja pelandak dalah						
None, scheduled for demolition.								
OTHER INFORMATION AS APPROPRIATI	E							
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)								
COMPILER, AFFILIATION Gabrielle L of Delaware, Center for Histo			ATE anuary 14, 1991					






HISTORIC AMERICAN BUILDINGS SURVEY


INDEX TO PHOTOGRAPHS


Thomas Montgomery House White Clay Creek Hundred New Castle County Delaware

HABS No. DE-


David L. Ames, Photographer Fall 1990 DE- -1 PERSPECTIVE OF WEST ELEVATION, LOOKING EAST DE- -2 ELEVATION OF WEST SIDE, LOOKING SOUTHEAST DE- -3 SECOND FLOOR, SOUTHEAST ROOM, LOOKING SOUTHEAST DE- -4 SECOND FLOOR, SOUTHEAST ROOM, LOOKING SOUTHEAST







HABS No.



UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY						
Delaware	New Castle		Newark Vicinity White Clay Creek Hundred						
HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR	NAME)	<u> </u>	HABS NO.					
Montgomery, Thomas House									
SECONDARY OR COMMON NAMES OF S	TRUCTURE								
The Newry									
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)									
Southeast corner, Rte 273 and Eagle Run Road, Newark, DE 19711									
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)									
ca. 1740(Herman, Architectur		N/A							
SIGNIFICANCE (ARCHITECTURAL AND				3					
is an important example of m for the second floor fielded									
roof framing.	pancied wair	and its eighteen	cir century	repairs to the					
STYLE (IF APPROPRIATE)	Control of the Contro								
Georgian MATERIAL OF CONSTRUCTION (INCLU	DE STRUCTURAL	SYSTEMSI							
		Brick wi		stone foundation. Brick					
bond on facade of main block SHAPE AND DIMENSIONS OF STRUCTU		· · · · · · · · · · · · · · · · · · ·							
Main block (period I): 36'3"	by 23'10"; Hy	phen (period II)	: 5'71/2" t	oy 2'1"; Kitchen					
(period II): 35'4 1/2" by 18'4"; Frame addition (period III): 28'3" by 18'4".									
EXTERIOR FEATURES OF NOTE Main block features brick dripcourse (for pent roof) between first and second floors on all elevations; brick dripcourse is also located at cornice level									
	on gable-end walls of main block.								
INTERNO DE FATURES OF NOTE (DECOS	UDE EL OOD BLANK	TE NOT OVETOUED		,					
INTERIOR FEATURES OF NOTE (DESCRIVATION NOTE)									
wall, southeast wall, southeast room, second floor, main block. Eighteenth-century repairs to common rafters of main block. Also significant is the hyphen between the main									
block and kitchen which features a staircase.									
MAJOR ALTERATIONS AND ADDITIONS		rvice wing and h	yphen added	l ca. 1830. Frame					
addition to service wing possibly dates to the twentieth century. Some interior alter-									
ations on the first floor, main block date to the late twentieth century.									
PRESENT CONDITION AND USE									
Presently in good condition; the house is used as office space.									
OTHER INFORMATION AS APPROPRIATE									
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)									
Bernard L. Herman, Architecture and Rural Life in Central Delaware (University of Tennesse Pross, 1987).									
COMPILER, AFFILIATION Bernard L.	Herman and Na	ncy Van Dolsen,	Univer-	DATE					
sity of Delaware, Center for	Historic Arch	itecture and Eng	ineering	January 14, 1991					