

**MID-ATLANTIC HISTORIC BUILDINGS & LANDSCAPE SURVEY
DIGITAL PHOTO LOG**

Huber Farm Complex
East side of Route 13, South of Boyds Corner Rd
McDonough Vicinity
New Castle County, Delaware

CHAD # 2008.01.0007.01
DE CRS # N-5181

Photographer: CHAD Staff

Date: October 2008

Photo #

Dwelling

- 1 Environmental view, looking northeast
- 2 View of west elevation, looking east
- 9 Perspective of south and east elevations, looking northwest
- 17 Interior, first floor: view of east and south walls of southwest room, showing
entrance to rear service wing, looking southeast
- 21 Interior, first floor: view of south and west walls of southeast room, showing
entrance to south central room, looking southwest
- 24 Interior, second floor: view of center hall, looking east
- 28 Interior, second floor: view of west and north walls of southwest room, showing
entrance to center hall, looking northwest
- 31 Interior, second floor: view of north and east walls of south central room, showing
entrances to bathroom and center hall, looking northeast
- 41 Interior, third floor: view of south wall of southwest room, looking south
- 42 Interior, basement: detail of east foundation wall of main block, showing floor
joists, brick, and stone elements



















